

68 - 6868071-2	Quarterway Elementary	2	Gymnasium	409	1971, 1993	Wood	1	SLAB	No Entry	D	Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868076-1	Rock City Elementary	1	Gymnasium	487	1971	Wood	1	CRAWL	3'-0"	D	Low	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	1
68 - 6868076-2	Rock City Elementary	2	Classrooms	1,086	1966	Wood	2	CRAWL	3'-0"	D	Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868076-3	Rock City Elementary	3	Primary Annex	414	1964	Wood	1	CRAWL	3'-0"	D	Low/Moderate	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	
68 - 6868076-4	Rock City Elementary	4	Classrooms	1,346	1969, 1971, 1974	Wood	2	CRAWL	3'-0"	D	Low/Moderate	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	
68 - 6868077-1	Rutherford Community	1	Gymnasium	427	1976, 1981	Block	1	SLAB	No Entry	C	Low/Moderate	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	1
68 - 6868077-2	Rutherford Community	2	2-Storey Classrooms	1,596	1976, 1981, 1977, 1977	Concrete	2	SLAB	No Entry	C	Moderate	H3	2016-06-22 Structural Upgrade Required	Ass-2016	1	1
68 - 6868077-3	Rutherford Community	3	Single Storey Timber Frame	705	1964, 1976	Wood	1	SLAB	No Entry	C	Moderate/High	M	2010-02-01 Non Structural Upgrade Required		1	
68 - 6868080-1	Seaview Elementary	1	Gymnasium	1,220	1987	Wood	1	CRAWL	2'-6"	D	Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	1
68 - 6868080-2	Seaview Elementary	2	Administration	884	1969	Wood	1	CRAWL	2'-6"	D	Low/Moderate	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	
68 - 6868080-3	Seaview Elementary	3	Classrooms	449	1968, 1979	Wood	1	CRAWL	2'-6"	D	Low/Moderate	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	
68 - 6868086-1	Uplands Park Elementary	1	Gymnasium	384	1981	Wood	1	SLAB	No Entry	D	Low/Moderate	L	2010-02-01 Meets Structural Life Safety Requirements	N	1	1
68 - 6868086-2	Uplands Park Elementary	2	Classrooms	2,538	1981, 1988	Masonry	1	SLAB	No Entry	D	Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6899022-1	Vast Centre	1	Classrooms	1,150	1954, 1960, 1971	Wood	2	BASEMENT	No Entry		Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	1
68 - 6868085-1	Woodbank Primary	1	Classrooms	1,364	1979, 1998	Wood	1	SLAB	No Entry	D	Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	1
68 - 6868085-2	Woodbank Primary	2	Library/Classroom	1,092	1966, 1969	Wood	1	SLAB	No Entry	D	Moderate/High	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868085-3	Woodbank Primary	3	Gymnasium	397	1969, 1998	Wood	1	SLAB	No Entry	D	Moderate	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868013-1	Woodlands Secondary	1	1959 3-Storey Classrooms	2,040	1959, 1966	Wood	3	CRAWL	3'-0"	D	High	M	2010-02-01 Non Structural Upgrade Required	N	1	1
68 - 6868013-2	Woodlands Secondary	2	1953 2-Storey Classrooms	3,714	1953, 1955	Wood	2	CRAWL	3'-0"	D	High	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868013-3	Woodlands Secondary	3	1953 Gymnasium	856	1953, 1955	Wood	1	CRAWL	3'-0"	D	High	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868013-4	Woodlands Secondary	4	1953 Shops & Cafeteria	1,233	1953, 1955	Wood	1	CRAWL	3'-0"	D	High	M	2010-02-01 Non Structural Upgrade Required	N	1	
68 - 6868013-5	Woodlands Secondary	5	1988 Band Building	221	1988	Wood	1	CRAWL	3'-0"	D	High	?	2010-02-01 ?	N	1	

TOTALS	91	3033
SUBTOTALS	91	3033